





IMPORTANT SAFETY INFORMATION. **READ AND FOLLOW ALL SAFETY INSTRUCTIONS**

IMPORTANT SAFETY INFORMATION. READ AND FOLLOW ALL SAFETY INSTRUCTIONS. Before wiring to power supply and during servicing or relamping, turn off power at fuse or circuit breaker. All servicing or relamping must be performed by qualified service personnel. Product must be grounded to avoid potential electric shock or other potential hazard. Product must be at locations and at heights and in a manner consistent with its intended use, and in compliance with Electrical Code and local codes.

SAVE THESE INSTRUCTIONS FOR FUTURE REFERENCE.




Step 1 Thread AC wires through swivel ball and mounting plate.



Step 2

Mount the mounting plate and swivel ball onto flat surface using screws.






Step 3 Mount canopy onto mounting plate and lock in place


with canopy set screws.

Step 4

Thread AC wire through stem and fasten to swivel








Step 5

Lock in place the stem mount bracket with luminaire bracket using the hex nut provided.




Step 6

Thread both uminaire wiring through bracket plate. Slip

luminaire at an angle over the lock-in grooves, and secure in place.





Step 7

Make electrical connections between AC wiring and I uminaire wiring (Refer to wiring diagram for more details). Cover electrical wiring with plate provided.

Wiring Diagram

STV | 1 -10V Dimming down to 10%

